

MX 91 MIXER

Parts list	Code	List € Price
Motor brushes (2)	0504	8,72
Ball bearing	0601	8,72
Waterproof seal	0607	11,39
Squeezing washer	0726	1,21
Lock button return spring	0767	2,57
Safety button return spring	0768	2,41
Wall bracket	0881	5,12
Long wall bracket	0881L	6,23
Strain relief 230 V	0950	1,53
Strain relief 115 V	0950.1	1,53
Switch (230 V / 115 V)	0965	23,15
Capacitor	0972	8,63
Capacitor + filter	0972.1	9,86
Warning label	1017	3,06
Dynamic label	1027	7,60
Label w/ serial number 230 V	1028	3,20
Label w/ serial number 115 V	1029	3,20
bearing holder + seal	1186	13,04
Emulsifying blade	7910	36,79
Lower bearing assembly	7916	21,14
Cutter blade	7917	23,09
Fan	7933	5,56
Lower bearing screws - Alu (3)	7950	0,75
Brace screws (4)	8317	2,85
Upper half handle (button side)	9002	34,16
Safety switch	9005	1,86
Locking switch	9007	1,77
Rotor 115 V	9008.11	139,06
Rotor 230 V	9008.12	139,06
Plug	9009	1,86
Control lever	9010	8,01
Power cord 230 V	9011	13,55
Handle screws (4)	9014	0,40
Motor housing brush holder	9015	46,23
Stator 230 V	9016	123,62
Stator screws (2)	9023	2,31
Ball bearing ring	9025	2,66
Braces (4)	9026	9,82
Stator 115 V	9038	123,62
Power cord 115 V	9040	16,94
Carbon brush wires 230 V	9043	5,81
Power cord (Australia)	9066	33,95
Power cord (UK)	9067	30,90
Complete handle w/ power cord 230 V	9100	98,69
Complete handle w/ power cord 115 V	9100.1	98,69
Half handle, label side (230V)	9101	35,01
Half handle, label side (115V)	9101.1	35,01
Speed control knob	9112	1,24
Complete foot assembly	9129	237,20
Foot assembly w/ bearing assembly	9130	168,81
Fitted shaft	9131	45,75
Carbon brush wires 115 V	9143	5,81
Shaft, lower bearing & cutter assembly	9164	80,93
Lower bearing screws - Stainless steel (3)	9902	0,75

